

# Inform

## ECN D34xx\_D3348

### Infineon TPM Update

ECN-No. SBOEM-D34xx\_D3348-211217

**Reason for ECN:** Revision update for several mainboards in order to solve the Infineon TPM Vulnerability issue

**Changes:** Onboard TPM module replaced by updated TPM module version based on latest Infineon Firmware V5.62.  
 This revision change has no influence on OS installation/drivers.  
 This revision change has no influence on mainboard/system approvals regarding safety and EMC.

Current Part No. / Revision	New Part No. / Revision
D3348-B23 GS1	D3348-B23 GS2
D3402-B21 GS2	D3402-B21 GS3
D3417-B21 GS1	D3417-B21 GS2
D3433-S22 GS1	D3433-S22 GS2
D3441-S20 GS1	D3441-S20 GS2
D3446-S11 GS2	D3446-S11 GS3
D3446-S21 GS1	D3446-S21 GS2

**Shipping details:** Shipment of the new revisions is expected from January 2018

**FTP Link "TPM Update / TPM Update Tool":**

[ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/Services/Software&Tools/Infineon TPM Vulnerability/](ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/Services/Software&Tools/Infineon_TPM_Vulnerability/)

Date	Revision Overview
12/2017	ECN Infineon TPM Update D34xx / D3348

**Published by department**  
Systemboard OEM Sales

**OEM FTP**  
<ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/>

Oem-marketing@ts.fujitsu.com

<http://www.fujitsu.com/fts/products/computing/pc/accessories/mainboards/>

All rights reserved, including intellectual property rights. Technical data subject to modifications and delivery subject to availability. Any liability that the data and illustrations are complete, actual or correct is excluded. Designations may be trademarks and/or copyrights of the respective manufacturer, the use of which by third parties for their own purposes may infringe the rights of such owner. For further information see [ts.fujitsu.com/terms\\_of\\_use.html](http://ts.fujitsu.com/terms_of_use.html)  
 © Copyright Fujitsu Technology Solutions GmbH 2017