Issue Publisher Content Contact January 2019 Mainboard OEM Sales D3446-S21 Revision Update Oem-marketing@ts.fujitsu.com



Inform ECN Overview D3446-S21 Industrial Mainboard

ECN-No. SB0EM-D3446S2-280119

Reason for ECN: Minor component (resistor) adjustment for improved boot / on-off behavior

Current Part No. / Revision	New Part No. / Revision
D3446-S21 / GS2	D3446-S21 / GS3

Shipping details: Shipment of the new revision starts from 02/2019

Released Operating Systems:

Mainboard Version	Win XP32/64	Win Vista	Win 7-32	Win 7-64	Win 8	Win 8.1-32	Win 8.1-64	Win 10 -64	Windows Server 2008 R2 (64)	Windows Server 2012 R2 (64)
D3446-S2			X	X			X	X	X	X

We highly recommend to use the latest released drivers.

ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/Products/Mainboards/Industrial&ExtendedLifetime/D344x-S/Drivers_D344x-S/Driver_

Initial released BIOS for D3446-S21: R1.13.0 Further BIOS ECN details are available here:

ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/Products/Mainboards/Industrial&ExtendedLifetime/D344x-S/BIOS_D344x-S/

IssueJanuary 2019PublisherMainboard OEM SalesContentD3446-S21 Revision UpdateContactOem-marketing@ts.fujitsu.com

Industrial Mainboard D3446-S2:

Mainboard	Version	Features	Reason for ECN	ECN Date
D3446-S2	D3446-S21 GS1		Initial Launch	09/2017
D3446-S2	D3446-S21 GS2 ¹⁾	iC236 Industrial ATX	TPM Firmware update due to Infineon vulnerability issue. See ECN <u>Inform_ECN_TPM-Update</u> for details	12/2017
D3446-S2	D3446-S21 GS3 ²⁾		Minor component (resistor) adjustment for improved boot / on-off behavior below 10°C mainboard environmental temperature (Change for GS2 included in GS3)	01/2019

^{* 1)} No field/customer HW upgrade to GS2! (TPM FW update possible by appropriate tool set, see Infineon_TPM_Vulnerability on OEM FTP) Factory shipments (mainboard production & RMA) move to GS2 from 12/2017

Date	Revision Overview
01/2019	D3446-S21 GS2 → GS3 (resistor adjustment)
12/2017	D3446-S21 GS1 → GS2 (TPM update) See ECN <i>Inform_ECN_D34xx_D3348_TPM-Update.pdf</i>
09/2017	Launch D3446-S21 with revision: GS1

Published by department

Systemboard OEM Sales

ftp://ftp.ts.fujitsu.com/pub/Mainboard-OEM-Sales/

Oem-marketing@ts.fujitsu.com

http://www.fujitsu.com/fts/products/computing/pc/accessories/mainboards/

All rights reserved, including intellectual property rights. Technical data subject to modifications and delivery subject to availability. Any liability that the data and illustrations are complete, actual or correct is excluded. Designations may be trademarks and/or copyrights of the respective manufacturer, the use of which by third parties for their own purposes may infringe the rights of such owner. For further information see ts.fujitsu.com/terms_of_use.html

© Copyright Fujitsu Technology Solutions GmbH 2019

^{* 2)} No field/customer HW upgrade to GS3! Factory shipments (mainboard production & RMA) move to GS3 from 02/2019

^{* 1) 2)} These revision changes have no influence on OS installation/drivers and mainboard/system approvals regarding safety and EMC.